# Digital Weighing Indicator CTI 400D

## **User Manual**





## CONTENTS

1. BEFORE INSTALLATION		4	-
2. INTRODUCTION	. <b></b> - !	5	-
2-1. Introduction	!	5	-
2-2. Cautions	!	5	-
2-3. Features	!	5	-
3. SPECIFICATION	(	6	-
3-1. Specification		6	-
3-2. Front Display		7	-
3-3. Key Operation	8	8	-
3-4. Key Combination	9	9	-
3-5. Real Panel	10	0 ·	-
4. INSTALLATION	1	1	-
4-1. External Dimension & Cutting Size	1'	1	-
4-2. Installation Components	1 <sup>-</sup>	1 ·	-
4-3 Load cell Installation	12	2	-
5. SET-UP	13	3	-
5-1. Set-up mode	13	3	-
5-2. Test Weight Calibration Mode (Using test weight)	14	4	-
5-3. Simulation Calibration Mode (Without Test weight)	18	8	-
5-4. Corner Adjustment	20	0	-
5-5. Axis Adjustment	2 <sup>.</sup>	1 ·	-
5-6. F-FUNCTION Setting	22	2	-
5-7. Test Mode	34	4	-
6. INTERFACE	38	8	-
6-1. Serial Interface	38	8	-
6-2. External Input	50	0 ·	-
6-3. Current loop	5 <sup>-</sup>	1 ·	-
6-4. Analog Output (4~20mA)	52	2	-
6-5. Analog Output (0~10V)	53	3 ·	-

6-6. Analog Output Setting	54 -
6-7. Print Interface	54 -
7. Error & Treatment	55 -
7-1. Load Cell Installation	57 -
7-2. Calibration Error	57 -
7-3. Digital Weighing Indicator	58 -

## **1. BEFORE INSTALLATION**

#### **Caution / Warning Marks**



This mark warns the possibility to arrive death or serious injury in case of wrongly used



This mark cautions the possibility to arrive serious human body injury or product lose in case of wrongly used.

#### **Copy Rights**

- 1. All Right and Authority for this Manual is belonged to CURIOTEC CO.,LTD.
- Any kinds of copy or distribution without permission of CURIOTEC CO.,LTD. will be prohibited.
- 3. This manual may be changed as the version is upgraded, without previous notice.

#### Inquiries

If you have any kinds of inquiries for this model, please contact your local agent or Head Office.

Head Office : Curiotec Co.,Ltd. Website : www.curiotec.com Email : srjeon@curiotec.com, curiotec@curiotec.com

## 2. INTRODUCTION

#### 2-1. Introduction

Thank you for your choice of CTI 400D Industrial Digital Weighing Indicator. This "CTI 400D" model is high-control performance weighing Indicator. This "CTI 400D" model has Output Interface, Serial Communication, Modbus, Analog Output and RS 232C Communication.

Please review and learn this instruction Manual and enjoy your process efficiency

with "CTI 400D" Digital Weighing Indicator.

#### 2-2. Cautions

1. Don't drop on the ground and avoid serious external damage on item.



- 2. Don't install under sunshine or heavy vibrated condition.
- 3. Don't install place where high voltage or heavy electric noise condition.
  - 4. When you connect with other devices, please turn off the power of item.
  - 5. Avoid from water damage.
  - 6. For the improvement of function or performance, we can change item specification without previous notice or permission.
  - 7. Item's performance will be up-dated continuously base on previous version's performance.

#### 2-3. Features

- 1. CTI 400D model is standard size indicator which is easy to install on the panel.
- 2. Front panel is covered with Polycarbonate film, strong against dust and water.
- 3. RS232 serial interface is standard installed
- 4. User can choose various options;
- RS232C / RS422, RS485

## 3. SPECIFICATION

### 3-1. Specification

Content		Specification		
	Load cell Excitation		DC +12V	
Digital Load	Connect with Load cell	Max 8EA		
Cell Interface	Communication with Load cell	RS485		
Communication Baud Rate			115,200bps	
Environment	Operating Temperature Range		-10°C ~ +40°C [14°F ~ 104°F]	
LINIONNEII	Operation Humidity Range		40% ~ 85% RH, Non-condensing	
			Test Weight Calibration Mode	
	Calibration Mode		Simulation Calibration Mode	
			Corner Adjustment	
		Axis Adjustment		
Function		6 digit	, 25.4mm(1inch) Red FND for Numbers	
rancaon	Display	7 digit, Red LED for Weight unit		
	Display	8 digit, Green LED for State alarr		
		12 digit Greed LED for Arrow		
	Key Pad		14pcs Standard Key pad	
	Additional Digital Input		4pcs external input key	
Communi-		Data Transference, Command Mode, Serial Printer Mode		
cation	Serial Port 1 (RS-232C)			
Power	AC : 110~240V, Ma	iximum	Power Consumption 14W	
Size	200mm(W) x 100mm(H) x 126.5n	nm(D) Weight : 1230g		

### 3-2. Front Display



#### 3-2-2. State LED Lamp

CONDITION MARK	CONTENT	
STEADY	When the weight is stable, ON.	
ZERO	When the current weight is zero, ON.	
TARE	When the "TARE" function is set, ON.	
HOLD	When the "HOLD" function is set, ON.	
TxD	When indicator sends date out through serial communication.	
RxD	When indicator receives date out through serial communication.	
PRT	When the weighing data is printed, ON.	
IN1	When external input 1 terminal is input, ON	
IN2	When external input 2 terminal is input, ON	
IN3	When external input 3 terminal is input, ON	
IN4	When external input 4 terminal is input, ON	
IN5	When external input 5 terminal is input, ON	
IN6	When external input 6 terminal is input, ON	

### 3-3. Key Operation

F1	- Press for 3 secs to enter Function setting mode.
F2	- Press for 3 secs, to enter "Hidden function" mode.
ZERO <sup>1</sup>	<ul> <li>Make the weight value to Zero</li> <li>(unable to use during "Hold" function or when the weight is zero)</li> <li>Number 1</li> </ul>
TARE	- Set the TARE Function - Number 2
TARE	- Set the TARE Reset - number 3
HOLD 4	- Set the "HOLD" Function - number 4
HOLD RESET	- When "HOLD" function is set, HOLD Reset - number 5
PART 6	- number 6
COUNT	- number 7
SUB TOTAL	- number 8
TOTAL	- number 9
PRINT	- number 0
CLEAR	- Cancel or Move to previous step.
ENTER	- Save and Move to next step.

F1 🛃 TARE <sup>2</sup>	Double tare setting
	(Once tare is set, Another tare is overlapped.)
	Print the Sub-total out
	Print the Grand-total out
	Delete the Sub-total weight
	Delete the Grand-total weight

#### 3-4. Key Combination

Tip

Max accumulated weighing count : 999,999times Over 999,999times  $\rightarrow$  return to "0" time Max accumulated weight display : 999999999 (g, kg, ton) Over 999,999,999 (g, kg, ton)  $\rightarrow$  return to "0" (g, kg, ton)

•	ON / OFF		OPTIO	N 1		•
	(1)POWER	NI (2400-	(5)Option		•	
		ER A(	OPTIO	N 2		
• <u>_</u>		POWF	(5)Option		•	•
		C C C C C C C C C C C C C C C C C C C	R X D T X D G N D C / L C / L	V + D + SHLD	CAL.	
		(2)External Input	(3)SERIAL I/F	(4)LOAD CELL		
MADE IN KO	DREA	DIGITAL INPUT	SERIAL I / F	D-LOAD CELL	CE	•

### 3-5. Real Panel

#### (1) AC Power input terminal

#### (2) External input terminal: User selectable 4EA

#### (3) Serial Interface terminal

Terminal	RxD	TxD	GND	C/L	C/L
RS – 232	Rx	Тх	GND	C/L	C/L

#### (4) Loadcell Input

Terminal	V+	V-	D+	D-	SHLD
Load Cell	V+	V-	D+	D-	SHEILD



Please make connection after checking the Comm. and other specification on the label attached on cover plate.

## 4. INSTALLATION

### 4-1. External Dimension & Cutting Size



### 4-2. Installation Components



### 4-3 Load cell Installation

Digital Load Cell Wire Connection (In case of CURIOTEC CO.,LTD.'s Load cell) It depends on the manufacturer of load cell. Please check the specification.



#### Load Cell Installation

- 1. You can connect Max 8pcs of same capacity Load cells at once. (350  $\Omega)$
- 2. You have to make horizontal balance on the ground.
- 3. If there is some temperature difference around Load cell, it can cause wrong weight measurement.
- 4. Don't do Welding job or Arc discharge around installation place. But, there is no choice, please disconnect power cable and Load cell cable.
- 5. If you measure static electricity material, please make earth between down part and upper part of Load cell.

## 5. SET-UP

### 5-1. Set-up mode

#### 5-1-1. How to enter Set-up mode





#### • How to enter each set mode

SET-UP mode		Press F1 key for 3 secs $\rightarrow$ F1
Test mode	Digital value	Press F1 key for 3 secs $\rightarrow$ TARE $\rightarrow$ ZERO 1
	Display	Press F1 key for 3 secs $\rightarrow$ TARE $\rightarrow$ TARE $\rightarrow$
	Key Input	Press F1 key for 3 secs $\rightarrow$ $\overrightarrow{\text{rare}^2}$ $\rightarrow$ $\overrightarrow{\text{rest}^3}$
	External Input	Press F1 key for 3 secs $\rightarrow$ $\overrightarrow{\text{TARE}^2}$ $\rightarrow$ $\overrightarrow{\text{HOLD}^4}$
	Analog out	Press F1 key for 3 secs $\rightarrow$ TARE <sup>2</sup> $\rightarrow$ COUNT
	Serial I/F(Basic)	Press F1 key for 3 secs $\rightarrow$ $\overrightarrow{\text{TARE}^2}$ $\rightarrow$ $\overrightarrow{\text{TOTA}^8}$
	Serial I/F(Option)	Press F1 key for 3 secs $\rightarrow$ $\overrightarrow{\text{TARE}^2} \rightarrow$ $\overrightarrow{\text{TOTAL}^9}$

\* Key to save data

key to cancel or back to previous step

### 5-2. Test Weight Calibration Mode (Using test weight)

#### 5-2-1. Calibration

Calibration is the process of adjusting weight balance between "Real Weight" on the Load Cell and "Displayed weight of Indicator". When you replace Load Cell or Indicator, you have to do Calibration process once again.

(When you enter t	he weight calibration	mode, tare, hole,	print function wo	ould be initialized.)
(			P	

Calibration key function					
Key button	Function	Key button	Function		
ZERO	No. 1	PART NO.	No. 6		
TARE <sup>2</sup>	No. 2	COUNT	No. 7		
TARE RESET	No. 3	SUB TOTAL	No. 8		
HOLD <sup>4</sup>	No. 4	TOTAL	No. 9		
HOLD RESET	No. 5 / Increase the number	PRINT	No. 0 / Decrease the number		
CLEAR	back to previous step	ENTER	Enter		



Ex : If you want to set Max Capacity as 50.00kg and division as 0.01kg, just input "50"

#### Step3. Decimal point and division setting





#### Step 6. Setting of 1st Max capacity (Multi calibration)

1) After

is displayed, enter the first max capacity using number keys

(0~9).



key for the next step.

The sum of the set weight of the 1<sup>st</sup> to 10<sup>th</sup> weights must be equal to the maximum weight. If the maximum weight is 100kg, 1<sup>st</sup> and 2<sup>nd</sup> set weight is 50kg each, then CAPA-1 and CAPA-2 only need to be finished.



#### Step 7. Calculating 1<sup>st</sup> span value

### 5-3. Simulation Calibration Mode (Without Test weight)

With "Simulation Calibration Mode", you can make simple calibration without test weight, let the indicator calculate "Load cells' max capacity" and "Max Output Rate(mV)".

#### Step 1 Simulation Calibration Mode Start



#### Step 2 Setting Max Capacity of Load Cell



input "50"

#### Step3. Decimal point and division setting





#### Step 6. Setting Max Capacity of Scale

- 1) Re-Setting Max Capacity of Scale in HF 23
- 2) HF 23 need not be re-set, If Capacity of Load cell and Capacity of Scale are the same.

### 5-4. Corner Adjustment

During the fifth step of both calibration, you can choose to proceed to "Corner Adjustment". In this step, you can adjust the error in the measured weight.



#### Step 1. Setting the Value of Test Weight



#### Step 2. Calculating the 1st span value



#### Step 3. Corner Adjustment of the 1st Digital Load Cell



After **LATE CU** is displayed, Indicator will calculate corner adjustment automatically for 10 secs.

- 2) After calculation, you will move to the step of "calculating the 2<sup>nd</sup> span value".
- 3) Repeat step 2 and 3 as many as the load cells you have. (HF-06)
- 4) After corner adjustment,
  - $\rightarrow\,$  Test Weight Calibration : move to the  $6^{th}$  step
  - $\rightarrow\,$  Simulation Calibration : finish the process

### 5-5. Axis Adjustment

During the fifth step of both calibration, you can choose to proceed to "Axis Adjustment". In this step, you can adjust the error in the measured weight.



#### Step 1. Setting the Value of Test Weight



#### Step 2. Calculating the 1<sup>st</sup> span value



#### Step 3. The 1<sup>st</sup> Axis Adjustment

- 1 After **LTLTCU** is displayed, Indicator will calculate axis adjustment automatically for 10 secs.
- 2) After calculation, you will move to the step of "calculating the 2<sup>nd</sup> Axis Adjustment"
- 3) Repeat step 2 and 3 as many as the half of the load cells you have.
- 4) After axis adjustment,
  - $\rightarrow\,$  Test Weight Calibration : move to the 6th step
  - $\rightarrow\,$  Simulation Calibration : finish the process

### 5-6. F-FUNCTION Setting

Function setting could set the indicator to operate perfectly with surrounding condition.

5-6-1. Starting F-FUNCTION Mode
1) Press the F1 key for 3seconds.
2) When SEE-UP is displayed, press
Function number     Setting value
<ul> <li>* F1 : Increase Function No.</li> <li>* F2 : Select Function No / Setting Value and enter the value</li> </ul>
3) Select Function number using number keys and Press enter.to adjust the function.
4) Enter the setting value and press and save it.
5) When the data is saved saved will be displayed and move to next
function number.
6) Press to cancel or back to the previous step.

	Equipment No. setting (ID No.)				
101	101 01 ~ 99 Enter ID No. using number keys				
	Weight–Back up Mode				
102		00	Normal mode		
102	•	01	Weight Back up Mode(Zero)		
	Weighing Data Save Method (Refer to the page 27)				
	•	00	Manual : Whenever input print key		
		01	Auto : At every steady states		
103		02	Auto : At the first steady states		
		04	Manual / Auto at every steady states		
		05	Manual / Auto at the first steady states		

#### **5-6-2. F-Function List** ("•" means the initial value of the product.)

#### **•**Weighing Data Save Method

	Weighing Data Save Method (Function no. 103)	Input Print	Print Output Data	Save data	
00	Manual : Whanavar input print kay	0	Current Weight	Current Weight	
	Manual . Whenever input print key	Х	Х	Х	
		0	Recent Steady	х	
01	Auto : At every steady states		Weight		
		Х	Steady Weight	Steady Weight	
		0	Recent Steady	V	
02	Auto : At the first steady states		Weight	~	
		Х	Steady Weight	Steady Weight	
04	Manual (Auto at overvictoady states	0	Current Weight	Current Weight	
04	Manual / Auto at every steady states	Х	Steady Weight	Steady Weight	
05	Manual / Auto at the first steady	0	Current Weight	Current Weight	
05	states	Х	Steady Weight	Steady Weight	

	Display Up-Date Speed				
104	05	01 ~ 09	01 : Slow ( 1 time per sec) ~ 09 : fast (60times per sec)		
	Buzzer sound (External input detection)				
109	•	00	Buzzer sound		
100		01	No Buzzer sound		
			Drib, bulk weight setting For Multi-calibration		
100	00	00 ~ 00	Drib, bulk weight setting For Multi-calibration 01 ~ 99%		
109	09	00 % 99	(of Maximum Capacity)		
			Unit		
		00	g		
110	●	01	kg		
		02	ton		
	-		Equipment and Print Language		
111	●	00	Korean		
		01	English		
			Zero Range (Near Zero)		
201	100	0 ~ 9999999	Zero range setting to confirm the empty state of scale.		
Auto Zero Range					
		-	Auto Zero Range		
202	00	00 ~ 99	Auto Zero Range If the scale becomes steady under the range of set value, the scale will		
202	00	00 ~ 99	Auto Zero Range If the scale becomes steady under the range of set value, the scale will display "0". (Unit: 0.25 gradation)		
202	00	00 ~ 99	Auto Zero Range If the scale becomes steady under the range of set value, the scale will display "0". (Unit: 0.25 gradation) Steady Range		
202	00	00 ~ 99	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will         display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time		
202 203	00	00 ~ 99 01 ~ 99	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time (Unit: 1 Digit)		
202 203	00	00 ~ 99 01 ~ 99	Auto Zero Range If the scale becomes steady under the range of set value, the scale will display "0". (Unit: 0.25 gradation) Steady Range Check steady state by setting steady range per unit time (Unit: 1 Digit) Steady condition check time		
202 203 204	00	00 ~ 99 01 ~ 99	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will         display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time         (Unit: 1 Digit)         Steady condition check time         Check steady state by setting steady condition check time per unit		
202 203 204	00 02 10	00 ~ 99 01 ~ 99 01 ~ 99	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will         display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time         (Unit: 1 Digit)         Steady condition check time         Check steady state by setting steady condition check time per unit         weight. (Unit: 0.1 sec)		
202 203 204	00 02 10	00 ~ 99 01 ~ 99 01 ~ 99	Auto Zero Range If the scale becomes steady under the range of set value, the scale will display "0". (Unit: 0.25 gradation) Steady Range Check steady state by setting steady range per unit time (Unit: 1 Digit) Steady condition check time Check steady state by setting steady condition check time per unit weight. (Unit: 0.1 sec) Digital Filter		
202 203 204 205	00 02 10 30	00 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will         display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time         (Unit: 1 Digit)         Steady condition check time         Check steady state by setting steady range per unit time         (Unit: 1 Digit)         Steady condition check time         Check steady state by setting steady condition check time per unit         weight. (Unit: 0.1 sec)         Digital Filter         Weak vibration       Strong vibration		
202 203 204 205	00 02 10 30	00 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will         display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time         (Unit: 1 Digit)         Steady condition check time         Check steady state by setting steady condition check time per unit         Check steady state by setting steady condition check time per unit         Weight. (Unit: 0.1 sec)         Digital Filter         Weak vibration       Strong vibration         99 (Weak)       ~ 01 (Strong)		
202 203 204 205	00 02 10 30	00 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time (Unit: 1 Digit)         Steady condition check time         Check steady state by setting steady range per unit time (Unit: 1 Digit)         Steady condition check time         Check steady state by setting steady condition check time per unit weight. (Unit: 0.1 sec)         Digital Filter         Weak vibration       Strong vibration         99 (Weak)       ~ 01 (Strong)         Zero key operation mode		
202 203 204 205	00 02 10 30	00 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time (Unit: 1 Digit)         Steady condition check time         (Unit: 0.1 sec)         Digital Filter         Weak vibration       Strong vibration         99 (Weak)       ~ 01 (Strong)         Zero key operation mode         Always active		
202 203 204 205 206	00 02 10 30	00 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time (Unit: 1 Digit)         Steady condition check time         (Unit: 0.1 big to be setting steady condition check time per unit weight. (Unit: 0.1 sec)         Digital Filter         Weak vibration       Strong vibration         99 (Weak)       ~       01 (Strong)         Zero key operation mode         Always active       Active under steady condition only		
202 203 204 205 206	00 02 10 30	00 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time (Unit: 1 Digit)         Steady condition check time         (Unit: 0.1 jeit)         Digital Filter         Weak vibration       Strong vibration         99 (Weak)       ~ 01 (Strong)         Zero key operation mode         Always active       Active under steady condition only         Tare Key operation mode		
202 203 204 205 206	00 02 10 30	00 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99 01 ~ 99 01 00 01	Auto Zero Range         If the scale becomes steady under the range of set value, the scale will display "0". (Unit: 0.25 gradation)         Steady Range         Check steady state by setting steady range per unit time (Unit: 1 Digit)         Steady condition check time         (Unit: 0.1 sec)         Digital Filter         Weak vibration       Strong vibration         99 (Weak)       ~ 01 (Strong)         Zero key operation mode         Always active       Active under steady condition only         Tare Key operation mode         Always active		

			Hold display weight when stable for set time			
	•	00	Disuse			
208		01~09	No changing after weight stable during setting time			
	Zero key Operation Range					
		00	Active within 2% of Max Capacity			
		01	Active within 5% of Max Capacity			
	•	02	Active within 10% of Max Capacity			
209		03	Active within 20% of Max Capacity			
		04	Active within 50% of Max Capacity			
		05	Active within 100% of Max Capacity			
		06	No limit			
× Wa	arning	: If you se	t "active over 10%", It can pass beyond the bounds of load cell input			
range	or ma	ximum cap	acity. In this case, "Cell-Err" or incorrect weight can be displayed.			
			Tare key Operation Range			
		00	Active within 10% of Max Capacity			
210		01	Active within 20% of Max Capacity			
210	$\bullet$	02	Active within 50% of Max Capacity			
		03	Active within 100% of Max Capacity			
	Auto Zero function under Tare state					
211	●	00	Disuse			
211		01	Use			
	Tare Delay Time					
			00 : Disuse			
212	00	00 ~ 10	01 ~ 10 : Use (Unit : 1 sec)			
		L	Tare Reset			
	•	00	Manual : Whenever input Tare key			
214		01	Auto : When the weight is under Zero range			
, , ,		02	Auto : After the weight becomes steady			
			Auto Tare reset Time			
			Set the tare reset after set value			
215	00	00 ~ 09	00 : Disuse			
			01 ~ 09 : use (Unit : 1sec)			
			Hold Mode			
216	●	00	Sample Hold : Hold and display the current weight			
210		01	Peak Hold : Hold and display the maximum weight while weighing			

		02	Average Hold : Hold and display the average weight during set time			
	Hold Delay Time					
217	00	$ _{00} \sim 10$	00 : Disuse			
217	00	00 10	01 ~ 10 : Use (Unit : 1	sec)		
	-	1	Hold reset a	t the I	near ze	ro
218		00	Disuse			
		01	Use			
	-	1	Hold rese	t dela	y time	
219	00	00 ~ 10	00 : Disuse			
			01 ~ 10 : Use (Unit : 1	sec)		
	_	1	Average	Hold	Time	
220	10	01 ~ 99	Hold average weight	during	g set tin	ne (Unit: 1 sec)
	1	1	Minus (-)	mark	display	
221		00	Display			
		01	No Display			
	Under UNPASS/OVERLOAD state, weight display					
222		00	Display			
		01	No Display			
External Digital Output 1 (IN1)						
	<u> </u>	00	Disuse		06	Hold Reset
		01	Zero		07	Hold/Hold Reset
233		02	Tare		08	Print
	L	03	Tare Reset		09	Sub-total Print
		04	Tare/Tare Reset		10	Total Print
		05	Hold			
	-	1	External Digita	al Out	put 2 (l	N2)
,	L	00	Disuse		06	Hold Reset
		01	Zero		07	Hold/Hold Reset
		02	Tare		08	Print
234		03	Tare Reset		09	Sub-total Print
		04	Tare/Tare Reset		10	Total Print
		05	Hold			
	_		External Digita	al Out	put 3 (I	N3)
		00	Disuse		06	Hold Reset
		01	Zero		07	Hold/Hold Reset
235		02	Tare		08	Print

		03	Tare Reset		09	Sub-total P	rint
		04	Tare/Tare Reset		10	Total Print	
		05	Hold				
External Digital Output 4 (IN4)							
		00	Disuse		06	Hold Reset	
		01	Zero	$\bullet$	07	Hold/Hold	Reset
220		02	Tare		08	Print	
230		03	Tare Reset		09	Sub-total Print	
		04	Tare/Tare Reset		10	Total Print	
		05	Hold				
			External Digita	l Out	put 5 (l	N5)	
		00	Disuse		06	Hold Reset	
		01	Zero		07	Hold/Hold	Reset
227		02	Tare		08	Print	
237		03	Tare Reset		09	Sub-total P	rint
		04	Tare/Tare Reset		10	Total Print	
		05	Hold				
External Digital Output (IN6)							
		00	Disuse		06	Hold Reset	
		01	Zero		07	Hold/Hold Reset	
220		02	Tare		08	Print	
230		03	Tare Reset		09	Sub-total Print	
		04	Tare/Tare Reset		10	Total Print	
		05	Hold				
			Zero state lamp	outp	ut stan	dard	
251		00	Near Zero				
251		01	Zero				
			Parity /	Stop	bit		
		00	DATA bit (8bit)		STOP bi	it (1bit)	parity bit (Non)
		01	DATA bit (8bit)		STOP bi	it (1bit)	parity bit (Odd)
		02	DATA bit (8bit)		STOP bi	it (1bit)	parity bit (Even)
301		03	DATA bit (7bit)		STOP bi	it (1bit)	parity bit (Odd)
		04	DATA bit (7bit)		STOP bi	it (1bit)	parity bit (Even)

		Communication Speed				
	00	2,400bps				
	01	4,800bps				
	• 02	9,600bps				
	03	14,400bps				
202	04	19,200bps				
302	05	28,800bps				
	06	38,400bps				
	07	57,600bps				
	08	76,800bps				
	09	115,200bps				
		Communication Mode				
	• 00	Simplex (Stream Mode)				
303	01	Duplex (Command Mode)				
303	02	Print Mode				
	03	Digital Load Cell Indicator Protocol				
"Check-Sum" under command mode (F303-01 only)						
204	• 00	Disuse				
504	01	Use (Refer the 6-1-10, included Error code)				
	Format under Stream Mode					
	• 00	Format 1 (19 byte)				
	01	Format 2 (22 byte)				
305	02	Format 3 (17 byte)				
505	03	Format 4 (22 byte)				
	04	Format 5 (15 byte)				
	, , ,	transference under stream mode				
	• 00	Continuously				
	01	Single time on every steady state				
306	02	Single time at the first steady point				
	03	Single time output after weighing finish				
	04	When input Print key				

Parity / Stop bit (Option Port)								
	• 00	DATA bit (8bit)	STOP bit (1bit)	parity bit (Non)				
	01	DATA bit (8bit)	STOP bit (1bit)	parity bit (Odd)				
308	02	DATA bit (8bit)	STOP bit (1bit)	parity bit (Even)				
	03	DATA bit (7bit)	STOP bit (1bit)	parity bit (Odd)				
	04	DATA bit (7bit)	STOP bit (1bit)	parity bit (Even)				
	Communication Speed (Option Port)							
	00	2,400bps						
	01	4,800bps						
	• 02	9,600bps	9,600bps					
	03	14,400bps						
200	04	19,200bps						
309	05	28,800bps						
	06	38,400bps						
	07	57,600bps						
	08	76,800bps						
	09	115,200bps						
		Communication N	Aode (Option Port)					
	00	00 Simplex (Stream Mode)						
210	01	Duplex (Command Mode)						
510	• 02	Print Mode						
	03 Modbus (RTU)							
	"Check-	Sum" under command n	node (F303-01 only) (Opt	tion Port)				
211	• 00	Disuse						
511	01	Use (Refer the 6-1-10, ir	cluded Error code)					
	· · · · · · · · · · · · · · · · · · ·	Format under Strear	n Mode (Option Port)					
	• 00	Format 1 (19 byte)						
	01	Format 2 (22 byte)						
312	02	Format 3 (17 byte)						
	03	Format 4 (22 byte)						
	04	Format 5 (15 byte)						
	, , , , , , , , , , , , , , , , , , ,	Transference under str	eam mode (Option Port)					
	• 00	Continuously						
212	01	Single time on every	Single time on every steady state					
515	02	Single time at the firs	Single time at the first steady point					
	03	Single time output af	Single time output after weighing finish					

		04	When input Print key		
	Print Format				
252		00	Continuously		
352		01	Single page		
Print Delay time					
354	00	00 ~ 09	Print after set time (Unit : 1 sec)		
		Paper W	/ithdraw Rate setting (After Continuous/Single Print)		
355	00	00 ~ 09	The line increases by 1 for set value increase after printing		
		Paper	Withdraw Rate setting (After Sub-total/Total Print)		
356	00	00 ~ 09	The line increases by 1 for set value increase after printing		
			Analog Output Applying Weight Range		
401		00	Absolute number (+,-)		
		01	Positive number (+)		
Analog Output Direction					
402		00	Forward		
402		01	Reverse		
			Analog Output Standard		
		00	Display value is Max Capacity		
		01	Display value is SP1 setting standard		
		02	Display value is SP2 setting standard		
403		03	Display value is SP3 setting standard		
		04	Display value is SP4 setting standard		
		05	Display value is Max Capacity		
		05	(When you set tare, the GROSS weight will be displayed)		

### 5-6-3. Hidden Function

How to enter Hidden function setting mode : Press <b>F2</b> for 3 seconds and input your password
Default password is <b>ZERO<sup>1</sup> ZERO<sup>1</sup> ZERO<sup>1</sup> ZERO<sup>1</sup> ZERO<sup>1</sup></b> (1111). Press after input your

password.

	Serial Number Check
HF01	Check your device's serial number
	S/W Version Check
HF02	Check the currently applied program version
	H/W Version Check
HF03	Check the currently applied hardware version
	DATE(Y,M,D) Check / Modification
HF04	Check the date or adjust when it is wrong.
	TIME(H,M,S) Check / Modification (24Hours)
HF05	Check the time or adjust when it is wrong.
	Digital Load Cell Setting
HF06	Set the number of digital load cell (able to be set 1~8)
	1st Digital Load Cell ID
HF07	Set the 1st digital load cell ID (able to be set 1~999999)
	2nd Digital Load Cell ID
HF08	Set the 2nd digital load cell ID (able to be set 1~999999)
	3rd Digital Load Cell ID
HF09	Set the 3rd digital load cell ID (able to be set 1~999999)
	4th Digital Load Cell ID
HF10	Set the 4th digital load cell ID (able to be set 1~999999)
	5th Digital Load Cell ID
HF11	Set the 5th digital load cell ID (able to be set 1~999999)
	6th Digital Load Cell ID
HF12	Set the 6th digital load cell ID (able to be set 1~999999)
	7th Digital Load Cell ID
HF13	Set the 7th digital load cell ID (able to be set 1~999999)
	8 <sup>th</sup> Digital Load Cell ID
HF14	Set the 8th digital load cell ID (able to be set 1~999999)

					1s	t DLC Sp	an Valu	9			
HF15	Chec	k the '	1st Dl	LC Spar	n Value						
	2nd DLC Span Value										
HF16	Chec	Check the 2nd DLC Span Value									
	3rd DLC Span Value										
HF17	Chec	k the 3	3rd D	LC Spa	n Value						
					4t	h DLC Sp	an Valu	e			
HF18	Chec	k the 4	4th D	LC Spai	n Value						
					5t	h DLC Sp	an Valu	e			
HF19	Chec	k the !	5th D	LC Spai	n Value						
					6t	h DLC Sp	an Valu	e			
HF20	Chec	k the	6th D	LC Spai	n Value						
					7t	h DLC Sp	an Valu	e			
HF21	Chec	k the <sup>·</sup>	7th D	LC Spai	n Value						
					8t	h DLC Sp	an Valu	e			
HF22	Chec	k the a	8th D	LC Spai	n Value						
					Maximun	n Capacit	y Weigh	t Check			
HF23	Chec	k the	max c	apacity	set unde	er test we	ighing ca	alibration.			
					Maximun	n Capacit	y Weigh	t Check			
HF23	Chec	k the I	max c	capacity	set unde	er test we	ighing ca	alibration.			
					l out(4-2	0mA) / V	out(0-1	0V) Set			
HE29	●	00	4-20	OmA							
111 25		01	0-10	V							
			I	out(4-	20mA) /	V out(0-	10V) Mi	nimum O	utput		
	Set N	1inimu	ım Ar	nalog O	utput.						
HF30		F1									
	Press		d to	enter n	ninum (-)	value. (at	ole to be	set -20~	+20 / de	efault : 0)	
				out(4-	20mA) /	V out(0-	10V) Ma	ximum C	output		
11524	Set N	/laxim	um Ar	nalog C	output.						
HF31	HF31 (F1)										
	11633					Password	Setting	361-20-	1207 46		
	Set t	he nas	swor	d for hi	dden fun	ction more	de (4 die	nit numbe	r)		
		1	2		3				sup 8	9	0
HF49	ZERC		ARE	RESET	HOLD	RESET	NO.	COUNT	TOTAL	TOTAL	PRINT
	1		2	3	4	5	6	7	8	9	0
	The	passw	ord c	ombina	ation can	be consi	sted of	0~9			

	Function Reset				
HF50	Change the all function from first time.				
	Factory Reset				
HF51	Change the all set value from Factory set value				
	1st Calibration Value				
HF90	Check the 1st Calibration value.				
	2nd Calibration Value				
HF91	Check the 2nd Calibration value.				
	3rd Calibration Value				
HF92	Check the 3rd Calibration value.				
	4th Calibration Value				
HF93	Check the 4th Calibration value.				
	5th Calibration Value				
HF94	Check the 5th Calibration value.				
	6th Calibration Value				
HF95	Check the 6th Calibration value.				
	7th Calibration Value				
HF96	Check the 7th Calibration value.				
	8th Calibration Value				
HF97	Check the 8th Calibration value.				
	9th Calibration Value				
HF98	Check the 9th Calibration value.				
	10th Calibration Value				
HF99	Check the 10th Calibration value.				



Before starting the TEST mode, Disconnect all of the indicators and equipment.



Key button	Test Mode	Key button	Test Mode
ZERO	Digital load cell Value	HOLD RESET	Output
TARE <sup>2</sup>	Display	PART	Analog Output(4~20mA / 0~10V)
TARE RESET	Key Input	COUNT	Communication Port
HOLD <sup>4</sup>	External Input	SUB TOTAL	Communication Port (Option)

#### 5-7-1. Digital value Deviation mode



#### 5-7-2. Key check mode



Input keys to check the input on the display.

Key button	Display	Key button	Display
ZERO	1	SUB TOTAL	8
TARE <sup>2</sup>	2	TOTAL	9
TARE RESET 3	3	PRINT	10
HOLD 4	4	ENTER	11
HOLD RESET	5	Ē	12
PART 6 NO.	6	F2	13
COUNT 7	7		

#### 5-7-3 External Input Check Mode



You can check if external input is working well.

#### 5-7-4. Analog Output 4~20mA, 0~10V Check Mode



You can simulate the output value of indicator from  $0(4mA,0V) \sim 100(20mA,10V)$ . If the analog output mode is  $4 \sim 20mA$ , "A" will be displayed. If the analog output mode is  $0 \sim 10V$ , "V" will be displayed.

You can check the analog output by entering the value using direction keys. (unit: 0.1) If the input value is over the maximum number, the practical analog output will be 100% value.

EX) In the case that the mode is 4~20mA, If you input 4.0, the output would be 4mA. In the case that the mode is 4~20mA, If you input 20.0, the output would be 20mA. In the case that the mode is 0~10V, If you input 4.7, the output would be 4.7V. In the case that the mode is 0~10V, If you input 10.0, the output would be 10V.

#### 5-7-5. Basic serial Interface Check Mode



- Under connecting PC and indicator, if test protocol is sent to indicator from PC, indicator will reply response data to the PC.

- Under connecting PC and indicator, if indicator's numeric button is pressed, test protocol will be sent to PC.

- Under connecting the RxD pin and TxD pin with

press key, if "Good" is displayed on FND, the communication state is normal. But if "bad" is displayed on FND, the communication state is abnormal.

#### 5-7-6. Option serial Interface Check Mode



- Under connecting PC and indicator, if test protocol is sent to indicator from PC, indicator will reply response data to the PC.
- Under connecting PC and indicator, if indicator's numeric button is pressed, test protocol will be sent to PC.
- Under connecting the pin 3 and pin4 with press

key, if "Good" is displayed on FND, the communication state is normal. But if "bad" is displayed on FND, the communication state is abnormal.



#### 5-7-7 Display check mode



- (1) Test mode for FND
- (2) Each segment on the display will come on one by one.
- (3) The 1<sup>st</sup>~7<sup>th</sup> segments will stay on until the 8<sup>th</sup> segment comes on.
- (4) After all of the segments turned on, the segments will repeat the steps 2~4 times more.

## 6. INTERFACE

### 6-1. Serial Interface

- 6-1-1. Standard serial interface terminal
- (1) RS 232



6-1-2. Option serial interface terminal (1) RS – 232



#### 6-1-3. Data Format

1	Header 1 H	leader 2	Data Byte 7 byte	Ur	nit		
	,	4	·,//	k	g	CR	LF
	Header1		Header2				
	OL : OVER LOAD	NT : NET-WEIG	NT : NET-WEIGHT (Tare is not set)				
	ST : STEADY	GS : NET-WEIG	GS : NET-WEIGHT (when setting TARE)				
	US : UNSTEADY						

(1) Data Format1 : not including ID No. (F305-00) -19byte

#### (2) Data Format2 : Including ID No. (F101 ID setting / F305-01) -22byte

ID Nu	mber		Неа	der 1		Head	der 2		Sp	oace	Dat 7	a Byte byte	Uı	Init		80
		,			,			,	+/_			/	k	g	CR	LF
											1	/				

Header1	Header2
OL : OVER LOAD	NT : NET-WEIGHT(Tare is not set)
ST : STEADY	GS : NET-WEIGHT (when setting TARE)
US : UNSTEADY	

(3) Data Format3 : Including ID No. & State (F101 ID setting / F305-02) -17byte

STX	ID Number	Header 1 Header 2	Data Byt 7 byte	e Decimal Point ETX
02h		<b>"W"</b> +	-	"P" 03h

Header1	Header2
OL : OVER LOAD	NT : NET-WEIGHT(Tare is not set)
ST : STEADY	GS : NET-WEIGHT (when setting TARE)
US : UNSTEADY	

#### (4) Data Format 4 : Including ID No. (F101 ID setting / F305-03) -22byte



ID Number : Function number 101

Header1	Header2
OL : OVER LOAD	NT : NET-WEIGHT(Tare is not set)
ST : STEADY	GS : NET-WEIGHT (when setting TARE)
US : UNSTEADY	

#### LAMP DISPLAY

Bit 0	Bit 1	Bit 2	Bit 3	Bit 4	Bit 5	Bit 6	Bit 7
ZERO	TARE	Gross Weight	Print	HOLD	1	STEADY	1

(5) Format 5 : 12byte



Byte	Cotent	Note
1	0x02	Start
2	+ or -	Sign
3	Weight Data 1	Upper byte
4	Weight Data 2	E
5	Weight Data 3	:
6	Weight Data 4	:
7	Weight Data 5	:
8	Weight Data 6	Lower byte
9	Decimal point	0 ~ 4
10	Xor Checkimg 1	4 upper bytes
11	Xor Checkimg 2	4 lower bytes
12	0x03	End

#### 6-1-4. Command Mode

Under "Command Mode", Indicator will recognize the receipt of Order based on 02h(STX) and 03h(ETX) signal, and transfers 06h(ACK), 15h(NAK).

Error Code	Error Code (When setting function number 304-01 or 311-01)												
0 (30h)	Normality	3 (33h)	Number data Error										
1 (31h)	Check-Sum Error	4 (34h)	Excess of write data's allowable range										
2 (32h)	Data length Error												

#### 6-1-5. Read COMMAND

		Length of transmission data (by indicator standards)				
Subject	Command	305/312	305/312			
		00,01,03,04 Setting	02 Setting			
Current Weight	STX ID RCWT ETX	22 byte	22 byte			
Current Data	STX ID RCWD ETX	44 byte	48 byte			
Sub-total data	STX ID RSUB ETX	29 byte	30 byte			
Sub-total counts	STX ID RSNO ETX	14 byte	14 byte			
Total data	STX ID RGRD ETX	29 byte	28 byte			
Current time	STX ID RTIM ETX	14	byte			
Current date	STX ID RDAT ETX	14	byte			
Tare weight	STX ID RTAR ETX	15 byte	18 byte			
Current P/N transmission	STX ID RPNO ETX	10	byte			

6-1-6	. Write	COMMAND
-------	---------	---------

		Length of trai (by indicate	nsmission data or standards)
Subject	Command	305/312	305/312
		- 00,01,03,04 Setting	- 02 Setting
Zero Setting	STX ID WZER ETX	8 k	oyte
Tare Setting	STX ID WTAR ETX	8 k	oyte
Tare Reset	STX ID WTRS ETX	8 k	oyte
Hold Setting	STX ID WHOL ETX		8 byte
Hold Reset	STX ID WHRS ETX		8 byte
Print	STX ID WPRT ETX	8 k	oyte
Sub-total Print	STX ID WSPR ETX	8 k	oyte
Total Print	STX ID WGPR ETX	8 k	oyte
Delete Sub-total	STX ID WSTC ETX	8 k	oyte
Delete total	STX ID WGTC ETX	8 k	oyte
Time Setting	STX ID WTIM Time (HHMMSS) ETX	14	byte
Date Setting	STX ID WDAT Date (YYMMDD) ETX	14	byte
P/N Setting	STX ID WPNO P/N ETX	10	byte

### 6-1-7. Read Command Details

	Current Weight (F305-00, 01, 03, 04 or F312-00, 01, 03, 04)															
4	SCII :	: STX I	D(2Bvt	te) RCV	VT ET>	<u>√</u> √	01, 03	, , ,		HEX :	02 30	31 52	43 57	′ 54 03	3	
		STX II	D RCW	/⊺ Stat	e1(2b	yte) Si	tate2(	2byte	) Sign	+/-(1b	yte) C	Curren	t Weig	ght (7	byte)	
F	Resp	Unit	(2byte	e) etx												
c	onse	State	1 : OL	(Overv	veight	:), ST(S	Steady	/), US(	(Unste	ady)						
		State	2 : NT	(Net V	Veight	t), GS(	Gross	Weig	ht)							
E	x)Stea	idy, No	ot usin	g Tare,	Curre	nt We	ight :	3.000k	kg			_			•	
	217			ĸ	C	••		5		,			,	+		
	02h	30h	31h	52h	43h	57h	54h	53h	54h	2Ch	4Eh	54h	2Ch	2Bh	30h	
	0	3		0	0	0	k	g	ЕТХ							
	30h 33h 2Eh 30h 30h 30h 6Bh 67h 03h Current Weight															
	Current Weight															
	Current Weight (F305-02 or F312-02)															
4	SCII :	: STX I	D(2byt	te) RCV	VT ETX	K				HEX :	02 30	31 52	43 57	′ 54 03	3	
		STX II	) RCM	/⊺ Stat	e1(1b	yte) St	tate2(	1byte	) P De	cimal	Point(	1byte	) Sign	+/-(1	byte)	
F	Resp	Curre	nt We	eight(7	byte)	Unit(2	byte)	ETX								
C	onse	State	1 : 0(0	Overw	eight),	, S(Ste	ady),	U(Un	steady	r)						
		State	2 : N(I	Net W	eight)	, G(Gr	oss W	/eight	)							
E	x)Stea	idy, No	ot usin	g Tare,	Curre	nt We	ight :	0.000	kg	-	•		0	0	0	
			ID	R	C	vv		3	N	P	3	<b>•</b>				
	02	h 30ł	1 31ŀ	ז 52h	43h	57h	54h	53h	4Eh	50h	33h	2Bh	30h	30h	30h	
	0	0	0	0	k	g	E	ТХ								
	30	h 30ł	1 30ł	1 30h	6Bh	67h	03h									

		Current Data Value															
					(F305	5-00, 0	01, 03,	04 or	F312	-00, 0 <sup>-</sup>	1, 03,	04)					
Α	SCII :	: STX I	D(2Byt	e) RC	WD ET	X				HEX :	02 30	31 52	43 57	44 03	3		
F	lesp	STX II	D RCW	/D <b>Da</b> f	te(6by	rte) Ti	me(6b	yte) P	/N(2b	yte) C	ount(	6byte)	)				
C	onse	Tare(	7Byte)	Curre	ent We	eight	(7byte	) Unit	(2byte	e) ETX							
E	x) Dat	te : Au	gust 1	2th 20	009, Ti	me : 1	2:00:0	0, P/N	: 15, (	Count	: 10tin	nes, Ta	re : 2.	000kg,			
	Curre	ent We	eight :	3.000	kg		-							12			
	STX			ĸ	C	w	D	0	9	0	8	1	2	1	2		
	02h	30h	31h	52h	43h	57h	44h	30h	39h	30h	38h	31h	32h	31h	32h		
	0	0	0	0	1	5	0	0	0	0	1	0	0	0	2		
	30h	30h	30h	30h	31h	35h	30h	30h	30h	30h	31h	30h	30h	30h	32h		
		0	0 0 0 + 0 0 3 . 0 0 0 k g ETX 30h 30h 2Bh 30h 30h 33h 2Fh 30h 30h 30h 6Bh 67h 03h														
	2Eh	30h	30h	30h	2Bh	30h	30h	33h	2Eh	30h	30h	30h	6Bh	67h	03h		
		Current Data Value (F305-02 or F312-02)															
	(F305-02 or F312-02) SCII : STX ID(2byte) RCWD ETX HEX : 02 30 31 52 43 57 44 03																
-		: STX ID(2byte) RCWD ETX       HEX : 02 30 31 52 43 57 44 03         STX ID RCWD P Decimal Point(1byte) Date(6byte) Time(6byte) P/N(2byte)															
D	locn	STX ID RCWD P Decimal Point(1byte) Date(6byte) Time(6byte) P/N(2byte)															
г С	nco	Coun	ι(ουγι	e) sig	)- / + ۱۱ اس√	abt(7	byte)		e(iby	10/ 51	JII+/-(	TDyte	) curr	ent			
C	,iise	Unit(	2bvte)	FTX	vvei	giit(/i	byte)										
F	x) Dat	te : Jar	uarv 1	lst 20'	14. Tin	ne : 12	2:00:00	. P/N :	34. C	ount :	10 tin	nes. Ta	re : 2.0	)00ka.			
C	Curren	t Weig	ht : 3.	000kg	,			, . ,	, -			,		,			
	STX		D	R	С	W	D	P	3	1	4	0	1	0	1	_	
	02h	30h	31h	52h	43h	57h	44h	50h	33h	31h	34h	30h	31h	30h	31h		
	1	2	0	0	0	0	3	4	0	0	0	0	1	0	+		
	31h	32h	30h	30h	30h	30h	33h	34h	30h	30h	30h	30h	31h	30h	2Bh		
	0	0	0	2	0	0	0	+	0	0	0	3	0	0	0		
	30h	30h	30h	32h	30h	30h	30h	2Bh	30h	30h	30h	33h	30h	30h	30h		
	k	g	ETX													ŝ.	
ſ																	
	6Bh	67h	03h														

	Sub-total															
	(F305-00, 01, 03, 04 or F312-00, 01, 03, 04)															
AS	ASCII : STX ID(2Byte) RSUB ETX HEX : 02 30 31 52 53 55 42 03															
Re	Response STX ID RSUB P/N(2byte) Sub-total Count (6byte)															
			Sub-t	otal (	11byte	e) Unit	t(2byt	<b>e)</b> ETX								
Ex)	P/N	l : 15,	Count	: 10 ti	mes, S	Sub-to	tal : 10	0.000K	G							
S	ТХ		ID	R	S	U	В	1	5	0	0	0	0	1	0	_
0	2h	30h	31h	52h	53h	55h	42h	31h	35h	30h	30h	30h	30h	31h	30h	ı
	0	0	0	0	0	1	0		0	0	0	k	g	ЕТХ	(	_
3	0h	30h	30h	30h	30h	31h	30h	2Eh	30h	30h	30h	6Bh	67h	03h		
								Sub-	total							
	(F305-02 or F312-02)															
AS	ASCII : STX ID(2byte) RSUB ETX HEX : 02 30 31 52 53 55 42 03															
Re	Response         STX ID RSUB P Decimal Point (1byte) P/N(2byte) Sub-total Count (6byte)															
<u> </u>			Sub-t	otal (	0byte	e) Unit	t(2byt	<b>e)</b> ETX								
Ex)	Cοι	unt : 1	0 time	s, Sub	-total	: 10.00	0Kg (3	3 Deci	mal P	laces)		•	0	0	0	
5	X		ID	R	5		B	<b>Р</b>	3		1	U				
	02ł	1 30I	n 31h	52h	53h	55h	42h	50h	33h	30h	31h	30h	30h	30h	30h	
	1	0	0	0	0	0	0	1	0	0	0	0	k	g	ET	X
	31ŀ	n 301	1 30h	30h	30h	30h	30h	31h	30h	30h	30h	30h	6Bh	67h	03h	
							Sı	ub-tot	al Co	unt						
AS	CII :	stx ie	D(2Byte	e) RSN	o etx				HE	<b>X :</b> 02	30 31	52 53	4E 4F	03		
Re	espo	nse	STX II	D RSN	O Sub	-total	Coun	t (6by	<b>te)</b> E1	ΤX						
Ex)	Ex) Sub-total Count : 123															
S	STX ID R S N O O O O 1 2 3 ETX															
0	2h	30h	311	521	n 53	h 4E	h 4F	<sup>-</sup> h 3(	0h 3	0h 3	30h	31h	32h	33h	03h	1

	Total															
	(F305-00, 01, 03, 04 or F312-00, 01, 03, 04)															
A	SCII :	: STX	ID(2By	te) RGR	d etx	(				HEX	:023	30 31 5	52 47	52 44	03	
R	lespo	nse	STX ID Unit(2	RGRD <b>byte)</b> [	<b>P/N(</b> 2 TX	2byte)	Total	Coun	t (6by	te) To	tal (1'	l byte)				
E	x) P/N	J:15,	Count	: : 10 ti	mes, 1	otal :	10.000	)kg								
	STX		ID	R	G	R	D	1	5	0	0	0	0	1	0	
	02h	30h	31h	52h	47h	52h	44h	31h	35h	30h	30h	30h	30h	31h	30h	
	0	0	0	0	0	1	0		0	0	0	k	g	ETX		
	30h	30h	30h	30h	30h	31h	30h	2Eh	30h	30h	30h	6Bh	67h	03h		
	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	]					]	т	atal							
							(E3(	10 15-02	otal or E31	2-02)						
A	SCII :	: STX	ID(2bv	te) RGF	D ETX	(	(150	5 02		HEX	:023	0 31 5	52 47	52 44	03	
	Response STX ID RGRD P Decimal Point(1byte) Total Count (6byte)															
R	Response Total (10byte) Unit(2byte) ETX															
E	Ex) Count : 10 Times, Total Weight : 10.000kg															
S	ТХ		ID	R	G	R	D	Р	3	0	0	0	0	1	0	
	021	h 30	h 31I	h 52h	47h	52h	44h	50h	33h	30h	30h	30h	30h	31h	30h	
	0	0	0	0	0	1	0	0	0	0	k	g	E	ТХ		
	30I	n 30	h 301	n 30h	30h	31h	30h	30h	30h	30h	6Bh	67h	03h	1		
								Curre	nt Tim	e						
A	SCII :	: STX	ID(2By	te) RTIN	л etx				HE	<b>X</b> :02	30 31	52 54	49 4[	D 03		
R	lespo	nse	stx id	RTIM	Curre	nt Tim	ne(6by	<b>te)</b> ET	Х							
E	x) Tim	ne : 12	2:00:00													
	STX		ID	F	2 7	<b>r</b>	I	M	1	2	0	0	0	0	El	<b>TX</b>
	02	h 30	)h 31	1h 52	2h 54	4h 49	9h 4	Dh 3	3 <b>1h</b> 3	82h	30h	30h	30h	30h	03h	
								Curre	nt Dat	:e						
A	SCII :	: STX	ID(2Byt	te) RDA	T ETX				HE	<b>x</b> :02	30 31	52 44	41 54	4 03		
R	Response STX ID RDAT Current Date(6byte) ETX															
E	x) Dat	te : Ja	nuary	1 <sup>st</sup> 2014	4			_	_		_					
S	ТХ		ID	R				<b>r</b>	1	<b>4</b>	0	<b>1</b>	0	<b>1</b>	ET	X
	02	h 30	h 31	h 52	h 44	h 41	h 54	4h 3	1h 3	4h 3	30h 3	31h 3	30h	31h	03h	

	Tare														
				(F3	05-00,	01, 03	3, 04 /	7 F312	- <b>00, 0</b> 1	I, 03,	04)				
ASCII :S	STX IE	D(2By	te) RTA	AR ETX	(			HEX :	02 30	31 52	54 41	52 03	3		
Resp	onse	S	TX ID	RTAR	Tare(7	oyte) E	TX								
Ex) Tare	Ex) Tare : 2.000kg														
STX	I	D	R	Т	Α	R	0	0	2	•	0	0	0	ETX	
02h	30h	31h	52h	54h	41h	52h	30h	30h	32h	2Eh	30h	30h	30h	03h	
							Та	re							
	(F305-02 or F312-02)														
ASCII :S	ASCII :STX ID(2byte) RTAR ETX HEX : 02 30 31 52 54 41 52 03														
Resp	Response STX ID RTAR P Decimal Point(1byte) Sign+/-(1byte) Tare(7byte) ETX														
Ex) Tare	Ex) Tare : 2.000kg														
STX	][]	ID	R	<b>. T</b>	Α	R	Р	3	+	0	0	0	2	0	
02h	30ł	1 31	h 52	h 54	h 41h	52h	50h	33h	2Bh	30h	30h	30h	32h	30h	
0	0		ЕТХ												
30h	30ŀ	n 03	h												
					C	urrent	: P/N <sup>-</sup>	Transn	nissior	I					
ASCII :	STX I	D(2By	/te) RF	'NO ET	ГХ			HEX :	02 30	31 52	50 4E	4F 03	5		
Resp	onse	5	TX ID	RPNO	P/N(2	byte)	ETX								
Ex) P/N	: 01														
STX		ID		R	Р	Ν	0	0	1	E	TX				
02	n 30	)h 3	81h	52h	50h	4Eh	4Fh	30h	31h	031	۱				

### 6-1-8. Write Command Details

	Zero (Sa	ame function as the	e Zero key)
ASCII : STX	(ID(2Byte) WZER ETX		HEX: 02 30 31 57 5A 45 52 03
Response	Normal : STX ID ACK ETX	Error : STX ID NAK	ETX
		Tare	
ASCII : STX	(ID(2Byte) WTAR ETX		HEX: 02 30 31 57 54 41 52 03
Response	Normal : STX ID ACK ETX	Error : STX ID NAK	ETX
		Tare Reset	
ASCII : STX	(ID(2Byte) WTRS ETX		HEX: 02 30 31 57 54 52 53 03
Response	Normal : STX ID ACK ETX	Error : STX ID NAK	C ETX
	Но	old (F305-02 or F31	2-02)
ASCII : STX	(ID(2byte) WHOL ETX		HEX: 02 30 31 57 48 4F 4C 03
Response	Normal : STX ID ACK ETX	Error : STX ID NAK	C ETX
	Hold	Reset (F305-02 or	F312-02)
ASCII : STX	(ID(2byte) WHRS ETX		HEX: 02 30 31 57 48 52 53 03
Response	Normal : STX ID ACK ETX	Error : STX ID NAK	C ETX
		Print	
	(Print data by the	port set as print r	node. (F303,310 -02)
ASCII : STX	(ID(2Byte) WPRT ETX		HEX: 02 30 31 57 50 52 54 03
Response	Normal : STX ID ACK ETX	Error : STX ID NAK	ETX
		Print Sub-total	
	(Print data by the	port set as print r	node. (F303,310 -02)
ASCII : STX	(ID(2Byte) WSPR ETX		<b>HEX :</b> 02 30 31 57 53 50 52 03
Response	Normal : STX ID ACK ETX	Error : STX ID NAK	C ETX
		Print Total	
	(Print data by the	port set as print r	node. (F303,310 -02)
ASCII : STX	(ID(2Byte) WGPR ETX		HEX: 02 30 31 57 47 50 52 03
Response	Normal : STX ID ACK ETX	Error : STX ID NAK	C ETX
		Delete Sub-tota	1
ASCII : STX	(ID(2Byte) WSTC ETX		HEX: 02 30 31 57 53 54 43 03
Response	Normal : STX ID ACK ETX	Error : STX ID NAK	C ETX
		Delete Total	
ASCII : STX	(ID(2Byte) WGTC ETX		HEX: 02 30 31 57 47 54 43 03
Response	Normal : STX ID ACK ETX	Error : STX ID NAK	ETX

						Time							
ASCII : STX	ID(2Byte)	WTIM	Time	(6byte	e) ETX								
Ex)12:00:00													
STX	ID	W	т	I	М	1	2	0	0	0	0	ETX	
02h 3	0h 31h	57h	54h	49h	4Dh	31h	32h	30h	30h	30h	30h	03h	
Response	Normal :	STX ID	ACK	ETX	Error :	stx id	NAK	ETX					
						Date							
ASCII : STX	ID(2Byte)	WDAT	Date	(6byte)	) ETX								
Ex) January	2 <sup>nd</sup> 2014												
STX	ID	W	D	A	т	1	4	0	1	0	2	ETX	
02h 3	0h 31h	57h	44h	41h	54h	31h	34h	30h	31h	30h	32h	03h	
Response	Normal :	STX ID	ACK	ETX	Error :	STX ID	NAK	ETX					
						P/N							
ASCII : STX	ID(2Byte)	WPNC	) P/N(	2byte)	ETX								
Ex) Change	P/N to 17	7											
STX	ID	W	P	N	I C	<b>)</b>	1	7	ETX				
02h 3	30h 31l	1 57I	n 50	h 4E	Eh 4F	<sup>=</sup> h 3′	1h 3	7h 0	3h				
Response	Normal :	STX ID	ACK	ETX	Error :	STX ID	NAK	ETX					

## TipHow to Calculate Check Sum

Sum the value from "STX" to "ETX" and converts to ASCII(2byte) and transfer.

Convert the Sum value(HEX) to ASCII and transmit(28byte) .

ex) The sum of HEX value from STX to ETX(02,30,31,52,43,57,54,03)is 1A6h.

Then, divide 1A6h by100h(1A6h/100h). the rest of result is A6h.

Calculated remainder value is A6h, then convertA6hto ASCII, 41(A), 36(6), and transfer

### 6-2. External Input

You can set each function of external Input through Function number 233~238.

#### 6-2-1. External Input configuration



#### 6-2-2. External Input connector connection

TERMINAL	11	12	13	14	15	16	IC
INPUT	IN1	IN2	IN3	IN4	IN5	IN6	IN COM

### 6-3. Current loop

Current loop is suitable for middle distance transmission since it is stronger than RS-232C against electric noise. (About 100M)

Maximum communication speed is 9,600.

#### 6-3-1. Current loop circuit composition



#### 6-3-2. Connection



RxD	TxD	GND	C/L	C/L
RS232	RS232	RS232	TxD	TxD

### 6-4. Analog Output (4~20mA)

Analog Output Interface (4~20mA) is a function to send weight data to external equipment which is adjusted by analog signal (Recorder, P.L.C and so on).

#### 6-4-1. Specification

Current Output	Accuracy	Temperature Coefficient	Maximum load impedance
0mA ~ 24mA	1/5,000	0.01%℃	500Ω MAX.

**P** Analog Output does not work during Calibration or "CELL-Err". When it stops, final output value remains. Please note that it is not suitable for system demanding high accuracy over 1/5,000.

#### 6-4-2. Circuit Composition and Connection

Current Output (Analog Electric Current, 4~20mA) is commensurate with the Weight Display Signal Input.





ACOM	AOUT
-	+

### 6-4-3. Output Adjustment

- (1) The product is initially supposed to output 0mA when the weight is 0, and 24mA when the weight is maximum.
- (2) User have to adjust analog output using Digital Multi-meter depending the environment.
- (3) How to adjust analog output
  - 1) Connect Digital Multi-Meter to Indicator (A Out Terminal).
  - 2) Enter HF30 "I out(4-20mA) / V out(0-10V) Minimum Output".
  - 3) Adjust and save the set number of Indicator to let digital multi-meter show minimum output. (When the set value is 04.00, the output would be about 4mA.)
  - 4) Enter HF31 "I out(4-20mA) / V out (0-10V) Maximum Output".
  - 5) Adjust and save the set number of Indicator to let digital multi-meter show minimum output. (When the set value is -4.00, the output would be about 20mA)

### 6-5. Analog Output (0~10V)

Analog Output Interface (0~10V) is a function to send weight data to external equipment which is adjusted by analog signal (Recorder, P.L.C, ....).

#### 6-5-1. Specification

Voltage Output	0~11V DC
Accuracy	1/5,000

**Tip** Analog Output does not work during Calibration or "CELL-Err". When it stops, final output value remains. Please note that it is not suitable for system demanding high accuracy over 1/5,000.

#### 6-5-2. Circuit Composition and Connection

Current Output (Analog Electric Current, 0~10V) is commensurate with the Weight Display Signal Input.



#### 6-5-3. Output Adjustment

- (1) The product is initially supposed to output 0V when the weight is 0, and 10V when the weight is maximum.
- (2) User have to adjust analog output using Digital Multi-meter depending the environment.
- (3) How to adjust analog output
  - 1) Connect Digital Multi-Meter to Indicator (A Out Terminal).
  - 2) Enter HF30 "I out(4-20mA) / V out(0-10V) Minimum Output".
  - 3) Adjust and save the set number of Indicator to let digital multi-meter show minimum output. (When the set value is 0.00, the output would be about 0V.)
  - 4) Enter HF31 "I out(4-20mA) / V out (0-10V) Maximum Output"..
  - 5) Adjust and save the set number of Indicator to let digital multi-meter show minimum output. (When the set value is 0.00, the output would be about 10V.)

### 6-6. Analog Output Setting

(1) Adjust output using switch.

(2) Enter "HF29 I out(4-20mA) / V out(0-10V) Set ". Select and save the output you want.

### 6-7. Print Interface

It can be connected with all kinds of Serial interface printer, but the printing format is already programmed and fixed with SE7200/7300 model.

	Korean(120-00)	English (120-01)
Continuous Print 121-00	날짜:       2011-05-10         시간:       18:00:10         장비번호:       1         장비 품번       순번       중량         1       10       1       1.330kg         1       10       2       5.350kg         1       10       3       2.358kg	DATE:       2011-05-10         TIME:       18:00:10         ID No:       1         ID PART SERIAL WEIGHT         1       10       1       1.330kg         1       10       2       5.350kg         1       10       3       2.358kg
Single Print 121-02	날짜: 2011-05-10 시간: 18:00:10 장비번호: 1 장비 품번 순번 중량 1 10 1 1.330kg 	DATE : 2011-05-10 TIME : 18:00:10 ID No : 1 ID PART SERIAL WEIGHT 1 10 1 1.330kg DATE : 2011-05-10 TIME : 18:00:10 ID No : 1 ID PART SERIAL WEIGHT 1 10 2 5.350kg
Grand-total Print	총 계           날짜 :         2011-05-10           시간 :         18:00:10           장비번호 :         1           품변         순변         중탕           1         15         105,21kg           2         21         172,92kg           :	TOTAL DATE : 2011-05-10 TIME : 18:00:10 ID No : 1 PART SERIAL WEIGHT 1 15 105.21kg 2 27 172.92kg  49 13 105.21kg 50 21 172.92kg TOTAL COUNT : 143 TOTAL WEIGHT : 700.35kg

#### 6-7-1. Print Format (Setting F-303 or 310-02)

**Tip** Date and Time data will be printed in Continuous Print mode such as Single Print Mode, if it is first print out.

### 6-8. BCD IN CARD ( Changing Product number )

#### 6-8-1. BCD IN card circuit composition



6-8-2. BCD IN card connection

### CONNECTOR D-SUB 25P FEMALE



PIN NO.	1	14	2	15	3	16	4	17	5
ROLE	IN1	IN2	IN3	IN4	IN5	IN6	IN7	IN8	IN COM
Function 310-01	1	2	4	8	10	20	40	-	-
Function 310-02	1	2	4	8	16	-	-	-	-
Function3 310-03	1	2	3	4	5	6	7	8	-

### 6-9. BCD OUT ( weight data output)

6-9-1. Circuit composition

6-9-2. Card switch setting

BCD OUTPUT			
	INDICATOR	EXTERN	AL
	BCD OUT		
	GND		
	Ļ	Ţ	

SWITCH	BASIC	MOTION
NON-INVERT	HIGH	LOW
INVERT	LOW	HIGH

#### 6-9-3. BCD OUT card specification

MAX Input Voltage 30V 500mA

#### 6-9-4. BCD OUT card connection



Role	Pin No.	Role	Pin No.
1X1	19	4X10000	28
2X1	2	8X10000	11
4X1	20	1X100000	29
8X1	3	2X100000	12
1X10	21	4X100000	30
2X10	4	8X100000	13
4X10	22	GND	32
8X10	5	Net-weight (HIGH)	31
1X100	23	Total weight (LOW)	31
2X100	6	GND	1, 14
4X100	24	Disuse	15
8X100	7	Decimal point 0.000	33
1X1000	25	Decimal point 0.00	16
2X1000	8	Decimal point 0.0	34
4X1000	26	Mark (Output : -)	17
8X1000	9	Disuse	35
1X10000	27	Disuse	18
2X10000	10	Overload	36

#### F309 9 , F310 00 F313 00

## 7. Error & Treatment

### 7-1. Load Cell Installation

Error	Cause	Treatment	Remarks
	1) Load cell broken		
	2) Load cell isolation		
	resistance error	1) Change the	
Weight Value is	3) Weighing part touches	summing board	
unstable	other devices or some	2) Check wiring status	
	weight is on the weighing	on Summing board	
	part		
	4) Summing Board Error		
Weight Value is			
increased regular	1) Load cell Error	1) Check Load cell	
rate, but not	2) Load cell connection Error	connection	
return to "Zero"			
		1) Check Load Cell	In case of more
	1) Load cell broken or	broken	loaded than Max
"OL" display	Indicator connection Error	2) Check Load cell	Capacity because
(Over Load)	2) More loaded than Max	correctly connected	of overlapped
	Capacity	3) Remove the weight	TARE used, it
		over-loaded	shows '-OL-'

### 7-2. Calibration Error

Display	Treatment
Err-04	In case of input more than Max capacity for Standard weight set-up
	1. Too high value of Amp. Gain
Err-06	2. Wiring D+/D- connected opposite
	3. No weight loaded
Err-08	In case of input the value that is not acceptable in FUNCTION
Err-A	Tough situation of the weight set-up because of unstable value

#### 7-3. Digital Weighing Indicator

Below error table show causing of error and treatment, when weighing process is not working or it cannot measure weighing due to indicator error.

Display	Cause	Treatment
"Sottin" 1. It displays "SETTIN" when the indicator 1		1. Please contact with your dealer or
Setun	is turned on, it is out of order EEPROM.	manufacturer directly.
1. Out of order H/W if "halt" is		1. Please contact with your dealer or
Hait	displayed	manufacturer directly.
"Lt Fur" 1. No connection between load cell and		1 Chack the DI /D, cable connection
	indicator	T. Check the D+7D- Cable connection.

X Under "Lt-Err", Zero key, Tare key, print key, and analog output(4-20mA/0-10V) will not be activated.

#### WARRANTEE CETIFICATION

This product is passed "Curiotec Co.,Ltd.'s strict quality test.

If there is defect of manufacturing or abnormal detection within warrantee period, please

contact our Agent or Distributor with this Warrantee certificate.

Then, we will repair or replace free of charge.

#### WARRANTEE CLAUSE

#### 1. The Warrantee period, we can guarantee, is one(1) year from your purchasing date

#### 2. Warrantee Exception Clause

- Warrantee period is expired.
- Any kinds of Mal-function or defection caused by Modification or Repair without Curiotec Co.,Ltd.'s permission.
- Any kinds of Mal-function, Defection, or External damage, caused by operator
- Any kinds of Mal-function, Defection, caused by using spare part from Non-Authorized Distributor or Agent.
- Any kinds of Mal-function, Defection, caused by not following Warnings or Cautions mentioned on this manual.
- Any kinds of Mal-function, Defection caused by "Force Majeur", like Fire, Flood.
- Without presentation of this "Warrantee Certification".
- 3. Other

- Any kinds of "Warrantee Certification" without authorized Stamp is out of validity

	Product	Digital Weighing
		Indicator
CURIOTEC Co.,Ltd.	Model	CTI 400D
#79, Myeongbongsan ro 352 beon-gil, Goangtan-		
mueon, Paju-si, Gyeonggi-Do, South KOREA, 413-855	Serial No.	
Website : <u>http://www.curiotec.com</u>		
Email : curiotec@curiotec.com	AUTHORIZED	(a) HE HE
		U1 == 10
Made in KOREA	STAMP	